

PROFORMA FOR SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

No. BWSSB/BLR/NW/H-604

Dated: 17/06/23



It is certified that an inspection team headed by AEE

(Name of Officers with designation) from B.W.S.S.B

(Name of Department/ Office) inspected the S.G. International Public school Saraswathipuram, Nandini layout, Bangalore

(Name & Address of the school) on (date of inspection) and found that the S.G. International Public School (Name of school) has safe drinking water facilities for the students and members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per norms prescribed by the Central/ State/ U.T. Govt.

The above is valid for a period of 2 years



Signature with Seal: [Signature]
Name: K.B. BASAHARAJA
Designation: Assistant engineer - BBMP
Name & Address of the Office / Department: Nandini layout Bangalore-96.

To S.G. International Public School Saraswathi.puram Nandini layout Bangalore

(Name & Address of the Institution)

* The filled up certificate should be either in Hindi or English. If it is issued in vernacular language, translated notarized version in English be uploaded along with the original vernacular certificate as a single pdf.

SG International Public School No. 18 Saraswathipuram, Nandini Layout, Bangalore-560 096 Ph: 080-23497428

[Signature] CHAIRMAN SHRIITHI SAGARA VIDYA SAMSTHE (P) C-18 Saraswathipuram, 2nd Circle, Nandini, Bangalore-560096



ಬೆಂಗಳೂರು ನೀರು ಸರಬರಾಜು ಮತ್ತು ಒಳಚರಂಡಿ ಮಂಡಳಿ

BANGLORE WATER SUPPLY AND SEWERAGE BOARD

Office of the Asst Executive Engineer,

No. 2, North-West-1 Sub Division, 1st 'N' Block,

Rajajinagar, B'lore-10 Ph: 22945176

No. BWSSB/AEENW-1/AE/RM/368

Dt: / / - 1 - 4 - 23

To,
The principle,
S.G.Intrenationl'school,
Nandini Layout,


Sir/Madam

Sub:-Regularisation of water supply and sanitary connection to your premises.

The school buildings have come up in your premises, the water or sanitary connections has regularized from this office. The school building conditions are good. The sanitary and water condition is good, there are no issues in water supply or in connection.


Thanking you

Your's faithfully



Asst Executive Engineer, 1/6

No.2, North-West-1 Sub Division, 1st 'N' Block,

Rajajinagar, B'lore-10



International Public School
No. 18, Saraswathipuram,
Nandini Layout, Bangalore-560 096
Ph: 080-23497428



CHAIRMAN
SG International Public School
No. 18, Saraswathipuram,
Nandini Layout, Bangalore-560 096



INDIAN ANALYTICAL TESTING LABORATORY



An ISO 9001:2015 Certified Laboratory

No.3, 3rd Floor, A Main Road, North Layout, NayandanaHalli, Near Indian Oil Petrol Bunk, Bangalore: 560039, Karnataka.

Mob No: 7899440170/8553345681 E-Mail: iatlabservice@gmail.com Web site: iatlabs.com

TEST CERTIFICATE


Certificate No.: IATL024/01/SCW/0026	Certificate Date: 20/01/2024
Issued To: SG INTERNATIONAL SCHOOL #28, Nandini layout Saraswatipuram Bangalore 560096	Date of Receipt: 18/01/2024
	Sample Code.: IATL024/01/SCW/0026
	Sample Collected By: IATLAB
Sample Description: Colorless, Transparent liquid	Description of Sample : Drinking Water

Sl. No.	Parameters	Test Method (Reference)	Limits AS per 10500:2012	Results
01	Color, Hazen Units	IS 3025 (Part 4)	2 Unit	<1.0
02	Odor	IS 3025 (Part 5)	Agreeable	Agreeable
03	Taste	IS 3025 (Part 8)	Agreeable	Agreeable
04	Turbidity, NTU	IS 3025 (Part 10)	1.0 NTU	0.00
05	pH @ 25 ^o C	IS 3025 (Part 11)	6.5 to 8.5	7.14
06	Chloride as Cl, mg/L	IS 3025 (Part 32)	250.0	84.00
07	Sulphate as SO ₄ , mg/L	IS 3025 (Part 24)	200.0	21.60
08	Alkalinity as CaCO ₃ , mg/L	IS 3025 (Part 23)	200.0	58.00
09	Total Dissolved Solids, mg/L	IS 3025 (Part 16)	500.0	210.20
10	Residual Free Chlorine, mg/L	IS 3025 (Part 26)	0.2	BDL
11	Total Hardness as CaCO ₃ , mg/L	IS 3025 (Part 21)	200.0	120.00
12	Copper as Cu, mg/L	IS 3025 (Part 42)	0.05	0.02
13	Iron as Fe, mg/L	IS 3025 (Part 53)	0.10	0.04
14	Calcium as Ca, mg/L	IS 3025 (Part 40)	75.0	28.44
15	Magnesium as Mg, mg/L	IS 3025 (Part 46)	30.0	19.80
16	Nitrate as NO ₃ , mg/L	IS 3025 (Part 34)	45.0	20.10
17	Aluminum as Al, mg/L	IS 3025 (Part 55)	0.03	0.02
18	Nitrite as NO ₂ , mg/L	IS 3025 (Part 34)	0.02	0.01
19	Fluoride as F, mg/L	IS 3025 /Part 60	1.0	0.50
20	Total Coliform, MPN/100 ml	IS:1622-1981	Not Detectable	Not Detected
21	E. coli, MPN/100 ml	IS: 1622-1981	Not Detectable	Not Detected

BDL-Below Detection Limit

Report Status: The tested water sample meets to acceptable limit as per IS 10500: 2012 for above Physical, Chemical and Microbiological Testing.

*****End of the Report*****

Analysed by: 



- Note: 1. The results listed pertain only to the tested samples and applicable parameters.
 2. Sample will be destroyed after 15 days from the date of issue of test certificate unless & otherwise specified.
 3. This report is not be reproduced either wholly or in part cannot be used an evidence in the court of law and should not be used In any advertising media without prior written permission.
 4. Sampling not done by us, unless specified.



ಬೆಂಗಳೂರು ನೀರು ಸರಬರಾಜು ಮತ್ತು ಒಳಚರಂಡಿ ಮಂಡಳಿ
BANGALORE WATER SUPPLY AND SEWERAGE BOARD

ಉಪ ವಿಭಾಗ / Sub Division : NW1
ಆರ್.ಆರ್.ಸಂಖ್ಯೆ / RRNo : NW112775/NND5-153
ಒಳಕೆದಾರರ ಸಂಖ್ಯೆ / Cons No : 981/24
Non Domestic
ಬಿಲ್ ಸಂಖ್ಯೆ / Bill No : NW112775/10
ಓದುವ ದಿನಾಂಕ / Rdg Date : 02/01/2024
ಪಾವತಿಗೆ ಕೊನೆಯ ದಿನಾಂಕ / Due Date : 17/01/2024

ಒಳಕೆದಾರರ ಹೆಸರು ಮತ್ತು ವಿಳಾಸ / Consumer Details
SGINTERNATIONAL SCHOOL SH

NO 18(CA), (PID NO) SARASWATHIPURAM MAHA

ಒಳಕೆ ವಿವರ / Consumption Details

ಇಂದಿನ ವಾಚನ / Pres Rdg : 1521.00
ಹಿಂದಿನ ವಾಚನ / Prev Rdg : 1501.00
ಒಳಕೆ / Consumption-Ltrs : 21.00

ಬಿಲ್ಲಿನ ವಿವರ / Billing Details

ನೀರಿನ ವೆಚ್ಚ / Water Charges : 500.00
ಮಾಪಕ ವೆಚ್ಚ / Meter Charges : 200.00
ಒಳಚರಂಡಿ ವೆಚ್ಚ / Sanitary Charges : 125.00
ಕೊ ಬಾ ಸ್ಯಾ ವೆಚ್ಚ / S.C For Borewell : 1000.00
ಇತರೆ ವೆಚ್ಚ / Other Charges : 1625.00
ಹಿಂದಿನ ಬಾಕಿ / Arrears : 0.00
ಬಡ್ಡಿ / Interest : 58.00
ಒಟ್ಟು ಮೊತ್ತ / Total Amount : 3508.00

ಮುಂಗಡ ಮೊತ್ತ / Adv Amount : 0.00
ಪಾವತಿ ಮೊತ್ತ / Net Amount Due : 3508.00

RUPEES THREE THOUSAND FIVE HUNDRED EIGHT
RUPEES ONLY

Previous Month Payment

Receipt No. / Pay Date / Amount / Mode / Paid at

530/28-12-2023/3566/Chequ/BWSSB-B1-233

AMOUNT PAYABLE AFTER DUE DATE 3566

LEVY OF CHARGES TOWARDS OC



Device No: 864666041524235
08-01-2024 14:11:07

ಸೆವಿಕ್ಸ್ ಟಾಂಕ್ / ಸೀವರ್‌ರನ್ನು ಸುರಕ್ಷಿತವಾಗಿ
FOR ENQUIRIES CONTACT: 080-22945176

Call 14420 for safe cleaning of Septic tank/Sewer.

ಬಲಮಂಡಲಯ ಒಳನುತ್ಪಾದಕ ಕಾಲ ಕೊಡಿಸುವ ಸುರಕ್ಷಿತವಾಗಿ ಸೇವೆಗಳು

ಈ ಕೆಳಗೆ ಪಾಲಿಸಾಕಾಳಿ ಸೇವೆಗೆ

www.bwssb.karnataka.gov.in/sakala_services